

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-10-09 10:24:56
Technician Name:Ricardo
Order no:
Service fee:
Notes:

Vehicle Information

Year:2021
Make:HONDA
Model:CR-V
VIN:MRHRW3850MP040027
Displacement:D 2.2 TCI-R
Odometer:44666 km
Vehicle Software Version:V10.42

Inspection Result

The following systems are OK:

- 1.PGM-FI/Diesel(Engine System)
- 2.AT(Automatic Transmission)
- 3.ABS(Anti-Lock Braking System)
- 4.SRS(Supplemental Inflatable Restraint System)
- 5.EPS(Electric Power Steering)
- 6.Gauge System
- 7.BCM(Body Electrical System)
- 8.Air Conditioning System
- 9.Immobilizer
- 10.PSR(Parking Sensor)