

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Sn:988579800333
Time:11/12/2024 08:13:02
Technician Name:Riaan
Customer Name:citton

Vehicle Information

Year:2018
Make:SUBARU
Model:Forester
VIN:JF2SJ9KC5JG104125
Odometer:57964 km
Vehicle Software Version:V10.52

Inspection Result

The following systems are OK:

- 1.EOBD
- 2.Engine(EGI)
- 3.Transmission(TM)
- 4.Brake Control(BC)
- 5.Body Control(BIU)
- 6.Airbag(AB)
- 7.Power Steering(PS)
- 8.Keyless Access with Push Button Start(SMT)
- 9.Automatic Light and Wiper(ALW)
- 10.Combination Meter(MET)
- 11.Multi-function Display(MFD)
- 12.Auto Start Stop(AS)
- 13.Power Rear Gate(PRG)
- 14.Headlight / Foglight(LT)