

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:11/07/2024 16:21:27

Technician Name:john

Vehicle Information

Year:2020

Make:TOYOTA

Model:Corolla Cross

VIN:AHTKFBAG800604915

Displacement:G 1.4 DOHC

Odometer:27196 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.ABS (Brake Control)
- 5.EMPS (Electronic Motor Power Steering)
- 6.SAS (Steering Angle Sensor)
- 7.SRS (Supplemental Inflatable Restraint System)
- 8.PCS (Pre-Collision System)
- 9.AC (Air Conditioning)
- 10.CM (Combination Meter)
- 11.NS (Navigation System)
- 12.BCM (Body Control Module)
- 13.CGW (Central Gateway)
- 14.DDM (Driver Door Motor)
- 15.PDM (Passenger Door Motor)
- 16.RLDM (Rear Left Door Motor)
- 17.RRDM (Rear Right Door Motor)
- 18.MSW (Master Switch)
- 19.RHS (Rain and/or Humidity Sensor)
- 20.FRS (Front Radar Sensor)
- 21.FRC (Front Recognition Camera)
- 22.FRCFLC (Front Recognition Camera (Front Lighting Control))
- 23.LC (Lane Control)
- 24.BSM (Blind Spot Monitor) Master

25.BSM (Blind Spot Monitor) Slave

26.CS (Clearance Sonar)