

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-08-05 09:50:09
Technician Name: Riaan
Customer Name: citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Make: AUDI
VIN: WAUZZZ8V3LA059203
Displacement: G 1.0 T-GDI KAPPA
Odometer: 100110 km
Vehicle Software Version: V10.24

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.42 Driver's Door Electronics
- 10.44 Power Steering
- 11.52 Passenger's Door Electronics
- 12.5F Information Electronics 1
- 13.76 Parking Aid
- 14.BB Rear Drivers Side Door Electronics
- 15.BC Rear Passenger Side Door Electronics