

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14485

Make	HAVAL	
Model	H9 2.0 LUXURY 4X4	A/T
Vin	LGWFF8A64JH90599	92
Engine Specifications	2.0	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2019
Km	118264
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Working Condition	•
Cluster	Not Applicable	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	<b>~</b>	Wiper Blades	Renewed	•

## **BOSCH VEHICLE INSPECTION**

					1
Oil Service		Km	Dip Stick	Within Specification	-
Oil Filter	Renewed	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	-	Fan Belt	No Cracks	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	-	Power Steering Belt	No Cracks	-
Brake Fluid	Within Specification	-	Aircon Belt	No Cracks	-
Antifreeze	Within Specification	-	Multi V belt	No Cracks	•
Rear Main Seal	Within Specification	-	Engine Mountings	Within Specification	-
Sump/Gasket	Within Specification	-	PCV Valve	Within Specification	-

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	-
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	-
Brake Master	Within Specification	•
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	-
Brake Hose	Within Specification	-

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

-Select-

WMPIE

## General Comments

Date of Inspection

08-Jul-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

