

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: mariska@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-08-02 13:55:33  
Technician Name: Wimpie F  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year: 2018  
Make: OPEL  
Model: Astra-K  
VIN: W0VBC6EA0JG106421  
Displacement: G 1.6 DOHC  
Odometer: 101801 km  
Vehicle Software Version: V10.48

## Inspection Result

BCM (Body Control Module) 1 problems exist

**1. B3110 Keyless Entry Transmitter 2 Battery**

**Malfunction**

The following systems are OK:

1. ECM (Engine Control Module)
2. EBCM (Electronic Brake Control Module)
3. PSCM (Power Steering Control Module)
4. SDGM (Serial Data Gateway Module)
5. SRS (Inflatable Restraint Sensing And Diagnostic Module)
6. IC (Instrument Cluster)
7. HC (HVAC Controls)
8. RADIO (Radio)
9. HVAC (Heating Ventilation Air-conditioning And Cooling)