Make	ТОУОТА	
Model	FORTUNER 2.4GD-6 R/B A/T	
Vin	AHTCB3GS202006874	ı
Engine Specifications	2.4	Diesel
Vehicle Type	SUV	
Service Plan	N/A	

Year	2019
Km	96838
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Good Condition	-
Cluster	Within Specification	•	Electric Windows	Within Specification	lacksquare

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Not Applicable		Oil Filler Cap	No Visible Leaks	lacksquare
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	lacksquare
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	lacksquare
Cabin Filter	Within Specification		Alternator Belt	No Cracks	lacksquare
Spark Plugs	Not Applicable		Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Good Condition		Multi V belt	No Cracks	•
Rear Main Seal	Not Applicable		Engine Mountings	Good Condition	•
Sump/Gasket	Not Applicable ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	lacksquare
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	lacksquare
Turbo	Within Specification	lacksquare
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	lacksquare

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	~
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	—
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	-
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	
Gearbox	Not Applicable	
Gear & Diff oil	Within Specification	
Auto Transmission	Within Specification	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	~
Handling	Good Condition	•

Concluding Remarks		
Book Tobaldo		Consul Community
Bosch Technician		General Comments
-Select-	 	



NEW Technician

RIAAN MEINTJIES



Date of Inspection

30-Jul-2024