

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:11/14/2024 08:49:47

Technician Name:Dries

Vehicle Information

Make:AUDI

VIN:WAUZZZGA3LA069373

Displacement:G 1.0 T-GDI KAPPA

Odometer:42749 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.29 Left Light Control
- 10.39 Right Light Control
- 11.42 Driver's Door Electronics
- 12.44 Power Steering
- 13.4B Multi-Function Module
- 14.52 Passenger's Door Electronics
- 15.5F Information Electronics 1
- 16.BB Rear Drivers Side Door Electronics
- 17.BC Rear Passenger Side Door Electronics
- 18.D6 Light Control Left 2
- 19.D7 Light Control Right 2