

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 2024-04-18 09:44:59
Technician Name: Lu-André
Order no:
Service fee:
Notes:

Vehicle Information

Make: SUBARU
Odometer: 96760 km
Vehicle Software Version: V10.42

Inspection Result

The following systems are OK:

1. EOBD
2. Engine (EGI)
3. Transmission (TM)
4. Brake Control (BC)
5. Body Control (BIU)
6. Airbag (AB)
7. Air Conditioner (AC)
8. Power Steering (PS)
9. Keyless Access with Push Button Start (SMT)
10. Combination Meter (MET)
11. Infotainment (INF)
12. Power Window (Driver) (PWD)
13. Power Window (Passenger) (PWP)
14. Power Window (Switch) (PWS)