| Make | RENAULT | |
|-----------------------|----------------------------|---|
| Model | CLIO IV 1.6 RS 200 EDC LUX | |
| Vin | VF15R4M0E50807595 | |
| Engine Specifications | 1.6 Petrol | • |
| Vehicle Type | H/B | |
| Service Plan | N/A | |

| Year | 2014 |
|---------------|-------------------|
| Km | 121621 |
| Transmission | Automatic |
| Colour | SILVER |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|----------------------|---|------------------|----------------|----------|
| Radio / Entertainment | Within Specification | - | Aircon Controls | Good Condition | ~ |
| Cluster | Within Specification | • | Electric Windows | Good Condition | — |

| Exterior | | | | | |
|-------------------------|----------------|---|--------------|----------------|---|
| Windscreen | Good Condition | - | Mag Wheels | Good Condition | • |
| Side Mirrors / Electric | Good Condition | - | Wiper Blades | Good Condition | • |

| BOSCH VEHICLE INSPECTION | | | | | |
|--------------------------|----------------------|--|---------------------|----------------------|----------|
| Engine | | | | | |
| Oil Service | SERVICE DUE Km | | Dip Stick | Within Specification | — |
| Oil Filter | Renewed | | Oil Filler Cap | No Visible Leaks | • |
| Fuel/Diesel Filter | Within Specification | | Fan Belt | No Cracks | • |
| Air Filter | Within Specification | | Fan belt Tensioner | Within Specification | • |
| Cabin Filter | Within Specification | | Alternator Belt | No Cracks | • |
| Spark Plugs | Within Specification | | Power Steering Belt | Not Applicable | • |
| Brake Fluid | Good Condition | | Aircon Belt | No Cracks | • |
| Antifreeze | Good Condition | | Multi V belt | No Cracks | - |
| Rear Main Seal | No Visible Leaks ▼ | | Engine Mountings | Good Condition | • |
| Sump/Gasket | No Visible Leaks ▼ | | PCV Valve | Within Specification | • |

| Braking System | | |
|--------------------|----------------------|---|
| Front Brake Pads | 80% | • |
| Front Brake Discs | Within Specification | • |
| Front Brake Sensor | Not Applicable | • |
| Rear Brake Pads | 60% | • |
| Rear Brake Discs | Within Specification | • |
| Rear Brake Sensor | Not Applicable | • |
| Rear Drums | Not Applicable | • |
| Rear Linings | -Select- | • |
| Brake Master | Good Condition | • |
| Hand Brake | Within Specification | • |
| Brake Calipers | Good Condition | • |
| Brake Hose | No Visible Leaks | • |

| Cooling System | | |
|-------------------|----------------------|----------|
| Radiator | Within Specification | • |
| Radiator Hoses | No Visible Leaks | • |
| Waterpump | Within Specification | • |
| Thermostat | Within Specification | • |
| Aircon Gas | Not Applicable | ~ |
| Aircon Pump | Within Specification | • |
| Aircon Condensor | Good Condition | • |
| Interior Fan | Good Condition | • |
| Interior Radiator | No Visible Leaks | • |

| Fueling System | | |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | - |
| Throttle | Within Specification | • |
| Turbo | Within Specification | • |
| Injectors | Within Specification | • |
| Fuel Pump | Within Specification | • |
| Fuel Lines | No Visible Leaks | • |

| Ignition System | | |
|-----------------|----------------------|----------|
| Ignition Coils | Within Specification | • |
| Glow Plugs | Not Applicable | • |
| Distrubutor | Not Applicable | ~ |
| HT Leads | Not Applicable | • |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------------|---|
| Steering Rack | Within Specification | - |
| Power Steering Pump | Not Applicable | - |
| Wheel Alignment | Within Specification | - |
| CV Joints | Good Condition | - |
| CV Boots | No Visible Leaks | - |
| Shocks Front | Good Condition | - |
| Shock Mountings Front | Good Condition | • |
| Shocks Rear | Not Applicable | - |
| Stabilizer Links | Good Condition | - |
| Wheel Bearings | Good Condition | - |
| Bearing Hubs | Within Specification | • |
| Control Arms | Good Condition | - |
| Sideshafts/Seal | No Visible Leaks | - |
| Propshaft | Not Applicable | - |
| Wheel Nuts/Studs | Good Condition | - |
| Tyres & Spare | Good Condition | - |
| Mag Wheels/Hub Caps | Good Condition | - |

| Transmission & Clutch | | |
|-----------------------|----------------------|----------|
| Clutch Kit | Not Applicable | — |
| Clutch Master | Not Applicable | — |
| Clutch Slave | Not Applicable | — |
| Clutch Cable | Not Applicable | T |
| Gearbox | Not Applicable | T |
| Gear & Diff oil | Within Specification | — |
| Auto Transmission | Within Specification | — |
| Gear Selector | Within Specification | — |
| Gear Linkages | Within Specification | T |

| Ignition System | | |
|------------------|------------------|----------|
| Diagnostics | No Fault Code | _ |
| Cyl Leakage Test | No Visible Leaks | _ |
| Road Test | Good Condition | _ |
| Handling | Good Condition | ~ |

| Concluding Remarks | | | |
|--------------------|--|--|--|
| | | | |
| | | | |
| | | | |

| Bosch Technician | General Comments |
|------------------|------------------|
| -Select- | |

| NEW Technician | Date of Inspection |
|-----------------|--------------------|
| RIAAN MEINTJIES | 14-Nov-2024 |



