

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 11/13/2024 16:23:36
Technician Name: Riaan
Customer Name: citton cars

Vehicle Information

Make: RENAULT
Model: CLIO IV
VIN: VF15R4M0E50807595
Displacement: G 1.0 T-GDI KAPPA
Odometer: 121631 km
Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. IC (Instrument Cluster)
4. TCM (Transmission Control Module)
5. SRS (Supplemental Inflatable Restraint System)
6. UCH
7. AC (Air Conditioning)
8. Variable P.A.S
9. UPC
10. Parking Prox Can
11. Radio
12. Hands-Free Module