

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-10-03 12:22:10

Technician Name:Raymond

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2019

Make:USAFORD

Model:EcoSport

VIN:MAJAXXMRKAKS07666

Displacement:G 1.2 DOHC

Odometer:92663 km

Vehicle Software Version:V10.86

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.GWM (Gateway Module A)
- 6.HVAC (Heating Ventilation Air Conditioning)
- 7.IPC (Instrument Panel Control Module)
- 8.PAM (Parking Aid Module)
- 9.PCM (Powertrain Control Module)
- 10.PSCM (Power Steering Control Module)
- 11.RCM (Restraint Control Module)
- 12.SCCM (Steering Column Control Module)