

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/01/2024 10:50:33

Technician Name:Christiaan

Vehicle Information

Year:2013

Make:PEUGEOT

Model:2008

VIN:VF3CU5FS0DY079407

Displacement:D 1.4 TCI-U2

Odometer:105710 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.Built-in Systems Interface(Bsi)
- 2.Engine ECU
- 3.Anti-lock Braking System (ABS) Or Electric Stability Program (ESP)
- 4.Air Bags
- 5.Audio-navigation Or Telematic Unit Or Connected Audio System
- 6.Rain And Brightness Sensor
- 7.Intrusion Alarm Siren
- 8.Alarm
- 9.Instrument Panel
- 10.Multiplexed Control Panel
- 11.Switch Module Under The Steering Wheel(Top Of Column)
- 12.Electric Power Steering
- 13.Steering Wheel With Integral Controls(Vci)
- 14.Air Conditioning
- 15.Parking Assistance
- 16.Matrix Screen Integral To The Instrument Panel