

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-21 11:41:39

Technician Name:Eugene

Order no:

Service fee:

Notes:

Vehicle Information

Make:AUDI

VIN:WAUZZZF59HA008136

Odometer:90790 km

Vehicle Software Version:V10.26

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.16 Steering Column Electronics Systems
- 8.17 Instrument Cluster
- 9.19 Data Bus OBD Interface
- 10.29 Left Light Control
- 11.39 Right Light Control
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.46 Comfort System Central Control Module
- 15.47 Sound System
- 16.52 Passenger's Door Electronics
- 17.5F Information Electronics 1
- 18.81 Selector Lever
- 19.CA Sunroof Control Module