

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15826

Make	MERCEDES-BENZ
Model	B 200 A/T
Vin	WDD2462432J308435
Engine Specifications	Petrol
Engine Specifications Vehicle Type	Petrol MPV

Year	2015
Km	86937
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	-

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Oil Service		Km	Dip Stick	Good Condition	-
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	-	Fan Belt	Good Condition	-
Air Filter	Good Condition	-	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	-	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	-	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•



Braking System
0 0 0

Front Brake Pads	-Select-	-
Front Brake Discs	Good Condition	-
Front Brake Sensor	Good Condition	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Good Condition	-
Rear Brake Sensor	Good Condition	-
Rear Drums	Not Applicable	~
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	-
Brake Hose	Good Condition	-

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	-

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	-
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	-
Stabilizer Links	Good Condition	-
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	-
Control Arms	Good Condition	-
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	-
Cyl Leakage Test	Good Condition	-
Road Test	Good Condition	•
Handling	Good Condition	-

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

