

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: pieter@boschgezina.co.za

Sn: 988579800333

Time: 2024-08-13 08:07:34

Technician Name: Dries

Order no:

Service fee:

Notes:

## Vehicle Information

Make: VW

VIN: AAVZZZAWZLU008525

Displacement: G 2.0 NU MPI

Odometer: 115706 km

Vehicle Software Version: V10.23

## Inspection Result

The following systems are OK:

1.01 Engine Electronics

2.03 Brake Electronics

3.08 Climate Control Module

4.09 Electronic Central Electric

5.15 Airbag

6.17 Instrument Cluster

7.19 Data Bus OBD Interface

8.44 Power Steering

9.5F Information Electronics 1