

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-08-12 09:32:06

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Make:VW

VIN:WVGZZZ5NZGW087755

Displacement:G 2.0 NU MPI

Odometer:87470 km

Vehicle Software Version:V10.23

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.10 Parallel Parking 2
- 6.15 Airbag
- 7.16 Steering Column Electronics Systems
- 8.17 Instrument Cluster
- 9.19 Data Bus OBD Interface
- 10.20 High Beam Assistant
- 11.25 Anti-Theft Immobilizer
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.52 Passenger's Door Electronics
- 15.53 Parking Brake
- 16.5F Information Electronics 1
- 17.61 Battery Regulation