Make	NISSAN		
Model	NAVARA 2.5DDTi SE A/T D/C P/U		
Vin	ADNCCAD23Z0009255		
Engine Specifications	2.5	Diesel	
Vehicle Type	D/C		
Service Plan	N/A		

Year	2022
Km	54903
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	<b>—</b>	Aircon Controls	Good Condition	•
Cluster	Good Condition	<b>V</b>	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	<b>—</b>	Mag Wheels	Good Condition	
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	<b>~</b>
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	<b>~</b>
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	<b>~</b>
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	<b>~</b>
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	<b>~</b>
Spark Plugs	Not Applicable	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks	<b>~</b>
Antifreeze	Within Specification	•	Multi V belt	No Cracks	<b>~</b>
Rear Main Seal	No Visible Leaks	<b>~</b>	Engine Mountings	Within Specification	<b>~</b>
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	<b>~</b>

Braking System		
Front Brake Pads	60%	-
Front Brake Discs	Good Condition	-
Front Brake Sensor	Good Condition	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Good Condition	-
Rear Linings	60%	-
Brake Master	Good Condition	•
Hand Brake	Within Specification	<b>T</b>
Brake Calipers	Within Specification	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	<b>~</b>

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Within Specification	•
Fuel Pump	No Visible Leaks	<b>~</b>
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	No Visible Leaks	
Wheel Alignment	Good Condition	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Good Condition	
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	<b>—</b>
Clutch Slave	Not Applicable	lacksquare
Clutch Cable	Not Applicable	<b>—</b>
Gearbox	No Visible Leaks	<b>—</b>
Gear & Diff oil	No Visible Leaks	<b>—</b>
Auto Transmission	Within Specification	lacksquare
Gear Selector	Not Applicable	lacksquare
Gear Linkages	Not Applicable	▼

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection



**PRETORIA** 

