

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-06-26 09:22:18

Technician Name: Raymond

Order no:

Service fee:

Notes:

## Vehicle Information

Make: NISSAN

VIN: ADNCCAD23Z0009255

Displacement: G 1.2 MPI

Odometer: 54908 km

Vehicle Software Version: V10.32

## Inspection Result

The following systems are OK:

1. ENGINE

2. ABS

3. METER/M&A

4. BCM

5. AIR BAG

6. TRANSMISSION

7. IPDM E/R

8. DIFF LOCK