

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:11/22/2024 09:28:07

Technician Name:Ricardo

## Vehicle Information

Make:NISSAN

Model:DATSUN GO

VIN:MDHZBAAD0Z0510166

Displacement:G 1.1 MPI

Odometer:76329 km

Vehicle Software Version:V10.48

## Inspection Result

The following systems are OK:

- 1.Engine Control Module(ECM)
- 2.Anti-lock Brake System(ABS)
- 3.Instrument cluster(IC)
- 4.Body Control System(BCM)
- 5.Supplemental Restraint System(SRS)
- 6.Electric Power Steering(EPS)
- 7.Intelligent Power Distribution Unit(IPDU)