

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-09-12 13:24:23
Technician Name:Riaan
Customer Name:citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Make:NISSAN
VIN:JN1JBNT32Z0102159
Displacement:G 1.4 DOHC
Odometer:91354 km
Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

- 1.ENGINE
- 2.ABS
- 3.METER/M&A
- 4.BCM
- 5.AIR BAG
- 6.HVAC
- 7.TRANSMISSION
- 8.MULTI AV
- 9.EHS/PKB
- 10.EPS/DAST 3
- 11.IPDM E/R
- 12.AIR PRESSURE MONITOR
- 13.ALL MODE AWD/4WD
- 14.ADAPTIVE LIGHT
- 15.CAN GATEWAY
- 16.AUTO BACK DOOR
- 17.CHASSIS CONTROL
- 18.3ch CAN GATEWAY