Make	MAHINDRA		
Model	PIK UP 2.2 mHAWK S4 P/U S/C		
Vin	MA1RA2VK2M2F	F10283	
Engine Specifications	2.2	Diesel	•
Vehicle Type	S/C		
Service Plan	N/A		

Year	2021
Km	109866
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	\
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Good Condition	_

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		91985 Km	Dip Stick	Within Specification	-
Oil Filter	No Visible Leaks	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks	-	Fan Belt	Not Applicable	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	-	Power Steering Belt	No Cracks	•
Brake Fluid	Good Condition	-	Aircon Belt	No Cracks	•
Antifreeze	Good Condition	-	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	No Visible Leaks	
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	lacksquare
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	~
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Good Condition	
Clutch Master	No Visible Leaks	
Clutch Slave	Good Condition	
Clutch Cable	Not Applicable	
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	\
Cyl Leakage Test	No Visible Leaks	•
Road Test	Within Specification	-
Handling	Within Specification	~

Concluding nemarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



