

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:kariska@boschgezina.co.za

Sn:988579800333

Time:2024-10-15 07:41:53

Technician Name:john

Order no:

Service fee:

Notes:

Vehicle Information

Year:2017

Make:MAZDA

Model:MAZDA3 / AXELA

VIN:JM6BN24Z2H0105092

Displacement:D 2.0 TCI R

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.F_BCM (Front Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.R_BCM (Rear Body Control Module)
- 5.RCM (Restraint Control Module)
- 6.ABS (Anti-Lock Brake System)
- 7.CMU (Connectivity Master Unit)
- 8.EPS (Electronic Power Steering)
- 9.SSU#1 (Start Stop Unit)