



## Vehicle Information

Brand: MAZDA	VIN: JM6DK2W7AK0410809	Plate Number: ht93tdgp
Model: MAZDA cx3	Mileage:	Color:
Year: 2018	Capacity: 2.0L	Status: Unset status
Engine: PE	Reference:	Date: 08.06.2024 10:54:07

## Automatic scanning results

System Name	Status/Count
01-PCM--Powertrain Control Module	Pass   No Fault
02-TCM--Transmission Control Module	Pass   No Fault
03-ABS--Antilock braking system	Pass   No Fault
04-F_BCM--Front Body Control Module	Pass   No Fault
05-R_BCM--Rear Body Control Module	Pass   No Fault
06-IC--Instrument Cluster	Pass   No Fault
07-RCM--Restraint Control Module	Pass   No Fault
08-EATC--Electronic Air Temperature Controller	Pass   No Fault
09-DCDC--DC to DC Converter Control Module	Pass   No Fault
10-CMU--Connectivity Master Unit	Pass   No Fault
11-AM--Amplifier Module	Pass   No Fault
12-SSU--Start Stop Unit	Pass   No Fault
13-EPS--Electronic-Controlled Power Steering	Pass   No Fault



---

Contact Information

Name:

Address: Pretoria Gauteng

Phone:

Email:

Website:

---

APP Version: 1.4.8