Make	ISUZU	
Model	D-MAX 1.9 Ddi HR L E-CAB	
Vin	ACVTFR87JMD114850	
Engine Specifications	1.9	Diesel
Vehicle Type	S/C	
Service Plan	18/01/2028	

Year	2023
Km	42242
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	18/01/2028

Interior					
Radio / Entertainment	Within Specification	<b>~</b>	Aircon Controls	Within Specification	_
Cluster	Within Specification	<b>—</b>	Electric Windows	Within Specification	_

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	<b>—</b>
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	•	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	•	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	•	Multi V belt	Within Specification	<b>T</b>
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	<b>~</b>

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	-
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	<b>V</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	-
Power Steering Pump	Within Specification	<b>—</b>
Wheel Alignment	Within Specification	<b>—</b>
CV Joints	Within Specification	<b>—</b>
CV Boots	Within Specification	lacksquare
Shocks Front	Within Specification	<b>—</b>
Shock Mountings Front	Within Specification	<b>—</b>
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	<b>•</b>
Wheel Bearings	Within Specification	<b>—</b>
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	<b>—</b>
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	-
Wheel Nuts/Studs	Within Specification	<b>—</b>
Tyres & Spare	Within Specification	<b>—</b>
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	<b>\</b>
Cyl Leakage Test	Within Specification	<b>~</b>
Road Test	Within Specification	-
Handling	Within Specification	<b>~</b>

Bosch Technician	General Comments
Ricardo Myburgh	
NEW Technician	Date of Inspection
	02-Sep-2024



**Concluding Remarks** 

