

Full Vehicle System AI Inspection Report

The Report is created by TOPDON

Repair Shop

SN:988987800929

Test Time:11/14/2024 09:15

Vehicle Information

Make:JPISUZU

VIN:ACVTFR87JMD114850

Mileage:0km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.IBS (Intelligent Battery System)
- 3.ABS (Anti-Lock Braking System)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.BCM (Body Control Module)
- 6.Meter
- 7.WAM (Wireless Access Module)