

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 2024-08-05 08:20:41

Technician Name: Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Make: NISSAN

Displacement: G 1.0 T-GDI KAPPA

Odometer: 159609 km

Vehicle Software Version: V10.32

Inspection Result

The following systems are OK:

1. ABS

2. BCM

3. AIR BAG