Make	VOLKSWAGEN	
Model	POLO VIVO 1.4 TRENDLINE (5DR)	
Vin	AAVZZZ6RZNU011709	
Engine Specifications	1.4 Petrol	•
Vehicle Type	H/B	
Service Plan	N/A	

Year	2022
Km	40551
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	•	Electric Windows	Within Specification	<b>•</b>

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		40558 Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Within Specification	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	-
Brake Fluid	Within Specification	•	Aircon Belt	Not Applicable	-
Antifreeze	Within Specification	•	Multi V belt	Within Specification	_
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	-
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	<b>\rightarrow</b>
Injectors	Within Specification	<b>~</b>
Fuel Pump	Within Specification	<b>~</b>
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	<b>•</b>
Wheel Alignment	Within Specification	<b>—</b>
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	<b>V</b>
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	<b>—</b>
Clutch Master	Within Specification	<b>—</b>
Clutch Slave	Within Specification	<b>T</b>
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Not Applicable	<b>—</b>
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	<b>~</b>

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Not Applicable	<b>-</b>
Road Test	Within Specification	-
Handling	Within Specification	<b>~</b>

Concluding Remarks			

Bosch Technician	
-Select-	•

General Comments						

NEW Technician	
HENNIE	





