

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 18324

Make	VOLKSWAGEN		
Model	POLO VIVO 1.6 COMFORTLINE TIP (5DR)		
Vin	AAVZZZ6RZMU01222	27	
Engine Specifications	1.6	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2021
Km	99904
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	-	Electric Windows	Working Condition	-

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Renewed	•

### **BOSCH VEHICLE INSPECTION**

Oil Service	SERVICE DONE Km	Dip	o Stick	Good Condition	•
Oil Filter	Renewed	Oil	Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks	Far	n Belt	No Cracks	-
Air Filter	Within Specification	Far	n belt Tensioner	Within Specification	-
Cabin Filter	Within Specification	Alt	ernator Belt	No Cracks	-
Spark Plugs	Within Specification	Pov	wer Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	Air	con Belt	No Cracks	•
Antifreeze	No Visible Leaks	Mu	ılti V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	En	gine Mountings	Within Specification	-
Sump/Gasket	No Visible Leaks	PC	V Valve	Within Specification	•



Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	-
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	-
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	-
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	-
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Within Specification	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

Raymond Mncube

**NEW Technician** 

## General Comments

Date of Inspection

24-Jan-2025



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

