

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 2024-09-09 13:28:47

Technician Name: Christiaan

Order no:

Service fee:

Notes:

## Vehicle Information

Make: NISSAN

VIN: ADNAPGD22ZR125983

Displacement: G 1.0 T-GDI KAPPA

Odometer: 97486 km

Vehicle Software Version: V10.32

## Inspection Result

The following systems are OK:

1. ENGINE

2. BCM