Make	HYUNDAI	
Model	H100 2.6D F/C D/S	
Vin	KMFZBX7BLPU01260	04
Engine Specifications	2.6	Diesel
Vahiala Tura		
Vehicle Type	D/S	

Year	2023
Km	58694
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	—	Aircon Controls	Within Specification	_
Cluster	Within Specification	V	Electric Windows	Within Specification	V

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	—	Fan Belt	Not Applicable	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	-	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	-	Multi V belt	Not Applicable	•
Rear Main Seal	Within Specification	-	Engine Mountings	Within Specification	-
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	—
Waterpump	Within Specification	•
Thermostat	Within Specification	lacksquare
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	lacksquare
Interior Fan	Within Specification	lacksquare
Interior Radiator	Within Specification	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	_

Ignition System		
Ignition Coils	No Visible Leaks	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	-
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	
Clutch Slave	Within Specification	
Clutch Cable	Not Applicable	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Bosch Technician		General Comments
Eugene J.v. Rensburg	¥	



NEW Technician

Concluding Remarks



Date of Inspection

16-Jul-2024