

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16367

Make	HYUNDAI		
Model	CRETA 1.6 EXECUTIVE		
Vin	MALC381CLKM5126	48	
Engine Specifications	1.6	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2019
Km	118780
Transmission	Manual
Colour	RED
Branch	Bosch Car Service
Warranty Plan	13/07/2026

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

## **BOSCH VEHICLE INSPECTION**

Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	-	Fan Belt	Good Condition	•
Air Filter	Good Condition	-	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	-	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	-	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	-	Multi V belt	Not Applicable	•
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	-
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•



40%	•
Good Condition	•
Not Applicable	•
40%	-
Not Applicable	-
Not Applicable	-
Good Condition	•
40%	-
Good Condition	•
Good Condition	•
Good Condition	-
Good Condition	-
	Good Condition Not Applicable 40% Not Applicable Not Applicable Good Condition 40% Good Condition Good Condition

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	-
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16367

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	<b>•</b>
Wheel Alignment	Good Condition	<b>•</b>
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	<b>•</b>
Shock Mountings Front	Good Condition	-
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	-
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	-
Tyres & Spare	Good Condition	-
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Good Condition	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	-
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	-
Cyl Leakage Test	Good Condition	-
Road Test	Good Condition	•
Handling	Good Condition	-

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

JHAUNDRE CRONJE

-Select-

### General Comments

Date of Inspection

11-Oct-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

