

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-11 07:43:54

Technician Name:john

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2019

Make:HYUNDAI

Model:Creta(GS)

VIN:MALC381CLKM512648

Displacement:G 1.6 MPI

Odometer:118784 miles

Vehicle Software Version:V10.40

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.IC (Cluster Module)
- 6.SJB (Smart Junction Block)
- 7.BCM (Body Control Module)
- 8.MDPS (Motor Driven Power Steering)
- 9.IMMO (Immobilizer)
- 10.CODE (Transmitter Code Saving)