

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 10/25/2024 09:11:29
Technician Name: Wimpie F

Vehicle Information

Make: BENZ
Model: 117.343 - CLA 200
VIN: WDD1173432N145457
Odometer: 93632 km
Vehicle Software Version: V10.88

Inspection Result

The following systems are OK:

1. FSCU - Fuel Pump
2. ME - MOTOR ELECTRONICS FOR COMBUSTION ENGINE (ECM)
3. VGS/DKG/DCT - Transmission Control Unit (TCM)
4. EFB - Electrical Parking Brake (EPB)
5. ES - Electronic Power Steering
6. ESP - Electronic Stability Program
7. TPC - Tire Pressure Monitoring System (TPMS)
8. SG_AWF - COLLISION PREVENTION ASSIST
9. EIS/EZS - Electronic Ignition Lock
10. ATA - Interior Motion Sensor
11. SCM - Steering Column Module
12. SD - Sliding Roof/Panoramic Sliding Sunroof
13. RevGUS_VL - Left Front Reversible Emergency Tensioning Retractor
14. RevGUS_VR - Right Front Reversible Emergency Tensioning Retractor
15. Driver-side SAM - Front Signal Acquisition And Actuation Module
16. AB - Supplemental Restraint System (SRS)
17. Audio - Audio Or COMAND
18. IC - Instrument Cluster
19. PTS - PARKTRONIC
20. ZAN - Audio/COMAND Display
21. COU[ZBE] - Audio/COMAND Operating Unit
22. DCU_FL - Left Front Door
23. DCU_FR - Right Front Door
24. AC - Air Conditioning
25. LIN: H3/1 - Alarm siren (AS)
26. LIN: N70 - Overhead control panel (OCP)

27.LIN: B95 - Battery sensor(BSN)

28.LIN: B38/2 - Rain/light sensor(RGLS)

29.LIN: N72/1 - Upper control panel(UCP)