Make	NISSAN		
Wake	MISSAN		
Model	ALMERA 1.5 ACENTA A/T		
Vin	MDHBBAN17Z	0714605	
Engine Specifications	1.5	Petrol	T
Vehicle Type	S/D		
Service Plan	N/A		

Year	2016
Km	109041
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	T
Cluster	No Fault Code	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	V
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	,	Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Not Applicable	•
Cabin Filter	Within Specification		Alternator Belt	Good Condition	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	Good Condition	•
Antifreeze	No Visible Leaks		Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	·	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	lacksquare
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	~
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	—
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	V



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	—
CV Joints	Within Specification	~
CV Boots	No Visible Leaks	—
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	—
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	~
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	—
Sideshafts/Seal	No Visible Leaks	—
Propshaft	Not Applicable	—
Wheel Nuts/Studs	Within Specification	—
Tyres & Spare	Within Specification	—
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	—
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	~
Gearbox	No Visible Leaks	~
Gear & Diff oil	No Visible Leaks	—
Auto Transmission	Within Specification	-
Gear Selector	Within Specification	—
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



