

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15212

Make	KIA		
Model	SPORTAGE 2.0 CRDi AWD A/T		
Vin	KNAPC813SD751471	8	
Engine Specifications	2.0	Diesel	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2013
Km	157837
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Not Applicable	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION

Oil Service		Km	Dip Stick	Within Specification	-
Oil Filter	Within Specification	-	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	-	Fan Belt	No Cracks	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	-	Power Steering Belt	No Cracks	•
Brake Fluid	Good Condition	-	Aircon Belt	No Cracks	•
Antifreeze	Good Condition	-	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	20%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	-
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	-

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	•
Aircon Condensor	Not Applicable	•
Interior Fan	Not Applicable	•
Interior Radiator	Not Applicable	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	-
Injectors	Within Specification	-
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Not Applicable	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

