

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-10-02 12:23:24

Technician Name:Riaan

Customer Name:citton

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2013

Make:KIAPLUS

Model:Sportage R(SL)

VIN:KNAPC813SD7514718

Displacement:D 2.0 TCI-R

Odometer:157856 km

Vehicle Software Version:V10.12

## Inspection Result

The following systems are OK:

- 1.Engine Control(CPF+)
- 2.Engine Control(CPF-)
- 3.TCM (Transmission Control Module)
- 4.ABS (Anti-Lock Braking System)
- 5.Airbag(Primary Crash)
- 6.Airbag(Secondary Crash)
- 7.AC (Air Conditioning)
- 8.BCM (Body Control Module)
- 9.SJB (Smart Junction Box)
- 10.Smart Key Unit
- 11.AHLS (Auto Headlamp Leveling System)
- 12.4WD Control
- 13.IMMO (Immobilizer)
- 14.CODE (Transmitter Code Saving)