Make	HYUNDAI		
Model	VENUE 1.0 TGDI FLUID DCT		
Vin	MALFC81AV	MM148311	
Engine Specifications	1.0	Petrol	<b>V</b>
Vehicle Type	H/B		
Service Plan	N/A		

Year	2021
Km	93744
Transmission	Automatic
Colour	BLUE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	<b>—</b>	Mag Wheels	Within Specification	-
Side Mirrors / Electric	No Fault Code	<b>~</b>	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	Not Applicable	•
Air Filter	Good Condition		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	Good Condition	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	_
Brake Fluid	No Visible Leaks		Aircon Belt	Good Condition	-
Antifreeze	No Visible Leaks		Multi V belt	Good Condition	_
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	<b>~</b>
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	No Fault Code	•
Turbo	No Fault Code	lacksquare
Injectors	No Fault Code	lacksquare
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	Not Applicable	
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	
Clutch Cable	Not Applicable	
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	No Visible Leaks	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



