

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Sn: 988579800333
Time: 11/11/2024 15:54:22
Technician Name: hennie

Vehicle Information

Year: 2021
Make: VW
VIN: WVVZZZ60ZMT150589
Displacement: G 1.4 DOHC
Odometer: 67160 km
Vehicle Software Version: V10.28

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.09 Electronic Central Electric
- 4.15 Airbag
- 5.17 Instrument Cluster
- 6.19 Data Bus OBD Interface
- 7.25 Anti-Theft Immobilizer
- 8.44 Power Steering
- 9.56 Radio

