

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14865

Make	MERCEDES-BENZ
Model	A 200d AMG A/T
Vin	WDD1760082J715130
Engine Specifications	Petrol
Engine Specifications Vehicle Type	Petrol H/B

Year	2018
Km	114835
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	-	Electric Windows	Working Condition	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Good Condition
Oil Filter	Renewed	Oil Filler Cap	No Visible Leaks
Fuel/Diesel Filter	No Visible Leaks	Fan Belt	No Cracks
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	No Cracks
Spark Plugs	Not Applicable	Power Steering Belt	Not Applicable
Brake Fluid	No Visible Leaks	Aircon Belt	No Cracks
Antifreeze	No Visible Leaks	Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Not Applicable	•
Rear Linings	80%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	-
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

JOB CARD NUMBER 14865

Steering & Suspension		
Steering Rack	Within Specification	-
Power Steering Pump	Not Applicable	-
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Good Condition	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Within Specification	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Raymond Mncube

NEW Technician

General Comments

Date of Inspection

24-Jul-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

