

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 11/11/2024 15:46:16
Technician Name: Ricardo

Vehicle Information

Year: 2023
Make: CHANGCHENG
Model: HAVAL JOLION FUEL
VIN: LGWEE5A5XPK615238
Displacement: G 1.4 DOHC
Odometer: 49620 km
Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module (UAES-4G15H&4G15K))
2. TCU (Transmission Control Unit 7DCT-300S) (UAES)
3. ESP (Electronic Stability Program)
4. ABM (Airbag Module)
5. KBCM (KOSTAL Elec Region Control System Body)
6. IP (Instrument Panel 7 Inch Yazaki)
7. GW (Independent Gateway)
8. AC (Air Conditioning) (BHTC)
9. RPAS (Rear Park Assistantsystem)
10. CSA (Combination Switch Assembly)
11. EPS (Electric Power Steering BOSCH)
12. F-PBOX (Front Power Box)
13. R-PBOX (Rear Power Box)
14. HUD (Head Up Display)
15. HUT (Head Unit (Harman))
16. HVSM (Heat Vent Seat Module (JIEWEN))
17. IFC (Intelligent Forward Camera)
18. RSDS_L (Left Radar Side Detection System)
19. RSDS_R (Right Radar Side Detection System)
20. SBWM (Shift By Wire Module (MANDE))
21. TPMS (Tyre Pressure Monitoring System)
22. WPC (Wireless Power Charger)