

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Name:

Address:

Telephone: N/A

Phone: 988579800333

Time: 12/09/2024 13:31:51

Technician Name: hennie

Vehicle Information

Make: BMW

Model: X1 xDrive20d

VIN: WBAHU320305G15361

Displacement: G 1.6 DOHC

Odometer: 114181 miles

Vehicle Software Version: V10.46

Inspection Result

The following systems are OK:

1. SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
2. HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
3. ZGM (Central Gateway Module)
4. ECM (Engine Control Module - DME/DDE)
5. TCM (Transmission Control Module - EGS)
6. LMV/VTG (Transfer Case)
7. ABS (Anti-Lock Braking System - DSC)
8. PMA (Parking Assistant)
9. EPS (Electronic Power Steering)
10. CAS (Car Access System - CAS/FEM/BDC)
11. LHML (LED Main Light Module, Left)
12. LHMR (LED Main Light Module, Right)
13. FZD (Function Center, Roof)
14. IC (Instrument Cluster - INSTR)
15. ECALL (Emergency Call)
16. CIC (Car Information Computer)
17. ZBE/CON (Controller)
18. AHM (Trailer Module)
19. AC (Air Conditioning - IHKA)