Make	KIA	
Model	PICANTO 1.2 SMART	
Vin	KNAB3512LLT615524	4
Engine Specifications	1.2	Petrol
Engine Specifications Vehicle Type	1.2 H/B	Petrol

Year	2021
Km	56723
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	—	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Good Condition	\rightarrow

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable	•
Air Filter	Within Specification	•	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Within Specification	~	Alternator Belt	Within Specification	•
Spark Plugs	No Fault Code	•	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	•	Aircon Belt	Within Specification	•
Antifreeze	No Visible Leaks	V	Multi V belt	Within Specification	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	-
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	-
Aircon Pump	No Fault Code	-
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	—
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	V



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	—
Wheel Alignment	Within Specification	—
CV Joints	Within Specification	—
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	T
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	—
Sideshafts/Seal	No Visible Leaks	T
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	—
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	\
Clutch Cable	Within Specification	V
Gearbox	No Visible Leaks	T
Gear & Diff oil	No Visible Leaks	V
Auto Transmission	Not Applicable	T
Gear Selector	Within Specification	T
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	~
Road Test	Within Specification	-
Handling	Within Specification	T

Concluding Remarks		
Bosch Technician		General Comments
Dries Olwagen	•	

NEW Technician	Date of Inspection
	02-Sep-2024



