

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-10-03 12:41:05

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Year:2019

Make:CHANGCHENG

Model:HAVAL H1

VIN:LGWED2A38KE615553

Displacement:G 1.2 DOHC

Odometer:95196 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

1.SRS (Supplemental Inflatable Restraint System)

2.IMMO (Immobilizer System)