

Year	2018
Km	96707
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	<b>•</b>	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	<b>~</b>
Side Mirrors / Electric	Within Specification	<b>—</b>	Wiper Blades	Renewed	<b>~</b>

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	<b>—</b>	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	-	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	lacksquare	Multi V belt	No Cracks	•
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	100%	•
Rear Brake Discs	Renewed	•
Rear Brake Sensor	Renewed	•
Rear Drums	Not Applicable	
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	_
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	_
Thermostat	Within Specification	-
Aircon Gas	Within Specification	-
Aircon Pump	Within Specification	_
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	lacksquare
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	lacksquare

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	
Control Arms	Within Specification	
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	lacksquare
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	<b>—</b>
Gearbox	Within Specification	<b>—</b>
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	<b>—</b>
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	<b>T</b>

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks		

Bosch Technician		General Comments
-Select-	_	

NEW Technician	Date of Inspection
WIMPIE	27-Sep-2024



**PRETORIA** 

