Make	NISSAN		
Model	NP200 1.6 A/C SAFETY PACK P/U S/C		
Vin	ADNUSN1D5U016649	97	
Engine Specifications	1.6	Petrol	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2019
Km	91284
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Good Condition	•
Oil Filter	Renewed		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	No Cracks	V
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	_
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	_
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	100%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	lacksquare
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	Within Specification	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	_
Throttle	Within Specification	lacksquare
Turbo	Not Applicable	lacksquare
Injectors	Within Specification	
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	lacksquare

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	No Fault Code	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	
Shocks Rear	Within Specification	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	
Control Arms	Within Specification	
Sideshafts/Seal	No Visible Leaks	
Propshaft	Not Applicable	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	lacksquare
Clutch Master	No Visible Leaks	lacksquare
Clutch Slave	No Visible Leaks	\
Clutch Cable	Not Applicable	V
Gearbox	Within Specification	V
Gear & Diff oil	No Visible Leaks	V
Auto Transmission	Not Applicable	—
Gear Selector	Good Condition	V
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection
	18-Jul-2024



Concluding Remarks

