

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-07-23 13:17:14

Technician Name: Mike Jones

Order no:

Service fee:

Notes:

## Vehicle Information

Make: NISSAN

Displacement: G 1.0 MPI KAPPA

Odometer: 127480 km

Vehicle Software Version: V10.32

## Inspection Result

The following systems are OK:

1. ENGINE

2. ABS

3. BCM

4. AIR BAG

5. EPS/DAST 3