

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 11/13/2024 13:49:08
Technician Name: Wimpie F

Vehicle Information

Year: 2013
Make: USAFORD
Model: Ranger / Mazda B-Ser
VIN: AFANXXMJ2NDB16768
Displacement: G 1.0 T-GDI KAPPA
Odometer: 163941 km
Vehicle Software Version: V10.86

Inspection Result

RCM (Restraint Control Module) 1 problems exist
1. B0090:93-8B Left Frontal Airbag Sensor

Continuous Memory DTCs

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. BCMII (Body Control Module)
4. FCDIM (Front Control/Display Interface Module)
5. IPC (Instrument Panel Control Module)
6. PCM (Powertrain Control Module)
7. TRM (Trailer Module)