

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:06/10/2025 11:35:41

Technician Name:Hennie

Vehicle Information

Year:2022

Make:HYUNDAI

Model:Venue(QXI)

VIN:MALFB81ALNM217032

Displacement:G 1.0 T-GDI KAPPA

Odometer:80230 km

Vehicle Software Version:V10.52

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)/ESP (Electronic Stability Program)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.AC (Air Conditioning)
- 6.IC (Cluster Module)
- 7.Integrated Body Control Unit-BCM
- 8.Integrated Body Control Unit-IMMO
- 9.Integrated Body Control Unit-SMK
- 10.Integrated Body Control Unit-TPMS
- 11.MDPS (Motor Driven Power Steering)
- 12.ICCU (Integrated Central Control Unit)
- 13.CODE (Transmitter Code Saving)