Make	MAHINDRA	
Model	PIK UP 2.2 mHAWK S4 4X4 P/U S/C	
Vin	MA1RA4VK2L2017651	
Engine Specifications	2.2	Diesel
Vehicle Type	S/C	
Service Plan	N/A	

Year	2020
Km	129326
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Good Condition	•
Cluster	Good Condition	V	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Not Applicable	~	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		129326 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Renewed	~	Oil Filler Cap	Renewed	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Renewed	•
Air Filter	Within Specification	—	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	—	Alternator Belt	Renewed	•
Spark Plugs	Not Applicable	—	Power Steering Belt	Renewed	•
Brake Fluid	Within Specification	—	Aircon Belt	Renewed	~
Antifreeze	Within Specification	lacksquare	Multi V belt	Renewed	~
Rear Main Seal	No Visible Leaks	—	Engine Mountings	Renewed	•
Sump/Gasket	No Visible Leaks	V	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	Good Condition	
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	No Visible Leaks	~
Radiator Hoses	No Visible Leaks	~
Waterpump	Renewed	~
Thermostat	No Visible Leaks	•
Aircon Gas	Within Specification	~
Aircon Pump	Good Condition	~
Aircon Condensor	Good Condition	V
Interior Fan	Good Condition	V
Interior Radiator	Good Condition	V

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	~
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	lacksquare
Distrubutor	Not Applicable	_
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	No Visible Leaks	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Renewed	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	

Transmission & Clutch		
Clutch Kit	Within Specification	-
Clutch Master	Within Specification	-
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	-
Gearbox	Good Condition	-
Gear & Diff oil	Within Specification	-
Auto Transmission	Not Applicable	-
Gear Selector	Good Condition	
Gear Linkages	Good Condition	V

Ignition System		
Diagnostics	No Fault Code	—
Cyl Leakage Test	Good Condition	\rightarrow
Road Test	Good Condition	~
Handling	Good Condition	•

Concluding Remarks		

Bosch Technician	Gener	al Comments
-Select-	_	

NEW Technician	Date of Inspection
HENDRIE	20-Dec-2024



